## **Power Off Timeout**

The activity time before auto power-off is now variable, rather than locked to one of the 4 preset values in prior firmware versions. \*

The default timeout is 3 minutes, 0 seconds. To change this, scan the Set Minute or Set Second barcode, then the digits to set the desired time, then Set Minute or Set Second again to end the programming. The time for each has a range of 00 to 60, and you must scan 2 digits. E.g., scan [Set Minute] [0] [5] [Set Minute] to set a 5 minute power off timeout.



Set Minute



2



4





Set Second













No Timeout (Scanner Always On)

<sup>\*</sup>This affects scanners with firmware SM3-c-1.30 or newer